G. R. S. 59] GPB -15,000 20 12 19

GENERAL AND REVENUE SECRETARIAT.

1899-1900
~~191~~.
(Dr Wkrai)

File No. 119

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Execution & repairs to the Jumma Masjid at Bijapore

PREVIOUS REFERENCES.	LATER REFERENCES.
	467-18 Hs 1-2

Order

An Estimate for Rs ~~130-4-0~~ 110-3-0 for repairing the Jumma Masjid at Gunpore, which has been prepared under the orders of the Executive Superintendent is sanctioned, the charge being met from the State Grant of Rs 15000 provided for ~~the Repairs~~ of in Govt. Pro No. 1083 dated 29th March 1899 for the repairs of Executive Buildings during the year 1899-1900.

No 576
Exec 745-92
Ex 1.
27 J. 12. 99.

2. The amount sanctioned in the foregoing para will be paid on presentation to the Comptroller duly ~~countersigned~~ signed by the Exec Superintendent

W.
Exec Secretary

To The Comptroller to Govt
with a copy of the Abstract Estimate

a1 30-11-22

Report

In submitting the appended Estimate for Repairs to Inspection Bungalow which amounts to about Rs 130-4-0 beg to state that there are no repairs now as there are proposed in the estimate under the orders of the Inspecting Secretary after personal inspection.

It seems there is at present a sum of Rs 333-4-5 at the credit of the unexpended

The following are the items of Works to be effected :—

I Removing old plaster & setting two layers of flat tiles in mortar with water pointering on the roof.

II Repairs to cracks & painting plants

III Whitewashing

B. Kundasamy Naidu
Inspecting Overseer

Abstract

Particulars of Works.	Quantity	Rate	per	Amount	Remarks.
Removing old plaster on the pf roof and replacing with layers of flat tiles and finishing with Chunam plaster	9.43	10	Sqc	94	
Whitewashin	26.53	3	"	4 15	
Pooting out plaints and filling up cracks——				6	
	al			104 1	
	ces			4	
7/12/99 Grand				110 3	

audu

Estimate of probable cost of effecting petty repairs & White washing Jumma Musjid at Mysore.

Items of work	No	Dimensions L	B	D	Contents	Total Contents	Remarks
Removing old plaster on the roof & setting two layers of flat tiles in mortar with mortar plastering	1	41	23		943	943	✓
Repairing cracks & rooting out plants growing on the roof		Terrace Sum Rs 6.					
Whitewashing main building the two coats of thick white wash							No deductions for openings have been made as arches & recesses are to be whitewashed
Walls running east to west	1	44	10½		924	✓	
Walls running north to south	1/3	39	10½		1229	✓	
Arch rooms	2	18	10		360	✓	
Do	2	7	10		140	✓	
							✓

Mysore
27th October 1899.

P. Kundaswamy Naidu
Engineer Dist. Dept.

~~Order No.~~

ad ~~Read~~ :- Govt Pro: no 576

muz 745-92

d/ 7th December 1899

sanctioning an Estimate

for Rs 110-3-0 for repairing

the Jumma Masjid at

Mysore

Order thereon

—"—

In continuation of

the above, the accompany

ing Supplemental

Estimate for Rs 60/-

~~for the repairs of~~ ~~estimate~~ sanctioned, the

charge being met from

the State Grant of Rs 1500

~~provided for in Govt Pro~~

No: 1083 d/ 29th March

muz 7105-92

1899 ~~for the repairs of~~

~~Mooznoi Buildings &c~~

No: 850 d/ 5th Feb 1900

muz 745-92 Govt

for the repairs of the masjid is

provided in the

Current years

Muzrai Budget Estimate

Govt Pro

~~1899-1900.~~

R6-a.

2. The amount sanctioned in the foregoing para will be paid on ~~presentation to the Comptroller~~ of a bill duly signed by the Mun: Superintendent.

A1

Municipal Secretary

To

The Comptroller & Govt.

with a Copy of the Estimate.

No 851

Superintendent's
Mysore Secretary's Office
Dated Bangalore 5th February 1900

Memo.

With reference to his letter of the 18th February 1900 submitting for sanction a Supplemental Estimate amounting to Rs 60- for the repair of the Jumma Masjid at Mysore, B. Kandasami Naidu Mysore Overseer is informed that a Government order sanctioning the Estimate has been issued this day and that he should have the work executed as early as practicable

Dft

Mysore Secretary
Superintendent

Sitha Villas
Mysore 1st February 1900.

To.

Rai Bhadur
A. Sreenivasah Charlu Esqr
Mysore Secretary
Bangalore.

Honored Sir.

I beg to submit herewith a supplimental Estimate for the repairs of Jummah Mosjed.

The works detailed in the estimate are very necessary without which the aims will not at all appear & therefore I humbly request you will kindly sanction the Estimate submitted

I beg to remain
Honored Sir
your most obedient & humble
Servant.

B Kunden Sing Rly
Mysore Overseer

Abstract

Items of work	Rate			Per	Amount		
Bengal terrace	69	10	..	Sqare	6	14	5
Planking (teakwood) replace for ceiling	83¼	"	6 "	Sft	3	4	6
Kwood reafer in the roof of main building front	2/3	2	12 "	c ft	2	"	"
To repair the holes and crack in planking	Lump Sum			Rs	1		
Brickwork in Mortar	21	.	2 6	c.ft	3	4	8
Mud wall	240	0	0 6	c ft	7	8	
Tiled coping	18	0	2 0	R ft	2	4	0
Chunam plastering	863	2	12 0	Sqare	23	11	9
White washing	427	0	3 0	Sqare	7	14	10
Total					57	14	2
Contengencies at 5%					2	1	10
Grand Total	Rupees				60	"	"

Mysore
1st February 1900

B Kundasawmyhair
Imprl Asstt.

whole wash.	1	25	15	375	
	1	7	14	98	
	1	18	17	306	
	1	67	19	1273	
	1	34	9	306	
	3	47	15	705	
Total				4227	4227

Bayonne
1st February 1900.

B Kundsammyhaid
Bayrai Quesco

MUZRAI

189

From The Muzrai Supdt.

To The Comptr to Govt.

Dated 28
Despatched 29. 3. 1900
Received
General No. 986
Muzrai F. No. 45 — 92
Enclosure No. 1.

Govt Pro Nos 576 Muz 745-92 and 850 Muz 745-92 dated respectively 7th December 1899 and 5th February 1900 sanctioning two estimates amounting to Rs 110-3-0 and Rs 60-0-0 respectively for repairing the Jumma Masjid at Mysore.

Adverting to para 2 of the above has the honor to forward herewith a measurement list for Rs 96-7-10 being the cost of work done up

to 27th March 1900
and to request that
the measurement list
in question may be
duly audited and returned
to this office for payment to the Contractor
the amount
being made payable at
the State Harbour Treasury.

Inlet Creek

To

The Comptroller
to Govt

No. 826
Mus F 45-92
Dy. 28th January 1901

In Continuation of
Govt order no 986
Mus F 45-92
dy 28th March 1900
has the honor to forward
herewith for audit a
further measurement
bill duly countersigned
for Rs 56-4-9 being
the actual cost now
incurred for the
repairs of the Jumma
Masjid at Mysore

as per

Original Estimate for Rs 1103-0
Sanctioned in Pro: No 5726 dt 4-12-99
Supplemental do: for Rs 50-00
do do dt 5/2/1900

Marginally noted
Estimates sanctioned
therefor, the charge
being debited to the
state Grant of Rs 15000
provided in the current
year's Mysrai Budget.
2. It is requested that
the bill may be enfaced
for payment in the
Mysore District Treasury.

By order

Mysr: Secy

Report.

An Estimate for Rs 110-3-a was sanctioned towards the repairs of the Jumma masjid at Mysore. The Contractor was paid Rs 96-7-10 on measurement Bill of 27th March 1900, Rs. 13-11-2 being then withheld.

Again a Supplemental Estimate for Rs 60/= was sanctioned in February 1900. I now beg to submit the completion Bill for Rs 42-9-7 on this account.

The Contractor has now to be paid Rs 42-9-7 the amount of the present measurement Bill plus Rs 13-11-2 being the amount withheld on measurement Bill of 27th March 1900, or in all Rs 56-4-9. The work has been satisfactorily executed.

Bangalore
23rd January 1901

B Munden Assy Engr.
Mukpri Overseer

Payment sanctioned
61
28/1/01

Supplemental Measurement Bill of actual work executed to Jumma Musjid at Mysore

Particulars	No	Measurement L	B	D	Contents	Total Contents	Remarks
Bengal terrace at the foot of parapet	2	11½	3		69	69	Sq ft
Replacing the rotten plank	1	8½	11"	1"	7 19/24	7 19/24	Cft
Teakwood paper to the roof of Main building	2	12	¼	⅛	¾	¾	Cft
To repair the holes & cracks in planking	L. S.					1/-	
Brick in mortar :-							
At the top of Compound wall by the side of old staircase	1	18	¾	⅔	4		
Steps to go up the Main building	6	1½	1	¾	6¾		
Screen wall to steps newly made	2	12	⅜	½	4½		
Total						20¼	Cft
Mud wall to replace the old one by the side of the central pond (south)	1	15	8	1¼	150	150	Cft
Tiles coping set in mortar	1	15			15	15	Rft
Chunam Plastering :-							
Around the central pond	4	22	4		352		
North Compound wall outside	1	45	3		135		
For steps & screen walls	1	18	2		36		
"	1	4	2		8		
South wing room	1	6	2		12		
To Mud wall to the south of central pond	2	15	8		240		
					783	783	Sq ft

Bangalore
23rd January 1901

B. Kondaswamy Sundara
Executive Engineer

కొప్పనూరు గ్రామంలో నిర్మించిన వ్యవసాయం
ఉత్పత్తుల విక్రయ కేంద్రంలో ఉంచడానికి
విన్నపము —

కొప్పనూరు గ్రామ పంచాయతీ పరిధిలో నిర్మించిన
ఈ కేంద్రాన్ని ప్రారంభోత్సవానికి శ్రీ కొండ్రాల్ల సుబ్బారావుగారి
చేత్తో ప్రారంభించాలని —

ఈ నిర్మాణానికి అయిన ఖర్చు వివరాలు
ఈ క్రింది విధంగా ఉన్నాయి. 1900 నాటికి ఈ
నిర్మాణం పూర్తి అయింది. 27 రకాల వ్యవసాయ
ఉత్పత్తులను ఇక్కడ నిల్వ చేయవచ్చు. ఈ
కేంద్రం ద్వారా రైతులకు 96-7-10 వరకు
రుణాలు ఇవ్వబడినవి. ఈ కేంద్రం ద్వారా
ఇంకా ఎన్నో వ్యవసాయ సంబంధిత పనులు
చేయవచ్చు.

7.4.1900

P. Subbarayudu
Contractor